

## CERTIFICATION OF COMPLIANCE

Contains: WG1031BHF2 Description: 9" x 9" Suction Outlet Cover

**Ratings:** Are Shown in the table below. Open Area: 23.18 sq-in  
 Certified to Comply with Section 1404 of the Virginia Graeme Baker Act (VGB) Pool & Spa Safety Act codified at 16 CFR part 1450. Initial Certification May 2011.

Manufactured: After November 1, 2020, by Division of Hayward Industries, Inc. at K4-A, 214028 Block K4- A, Export Processing Zone Wuxi New District Jiangsu Province PRC 214028, China.e  
 Certified by Hayward Industries Inc. 400 Connell Drive, Suite 6100, Berkeley Heights, NJ 07922, Phone 908-355-7995  
 Contact at [www.hayward-pool.com](http://www.hayward-pool.com)

Record Custodian is Customer Service at [www.hayward.com](http://www.hayward.com).

Email: <https://www.hayward-pool.com/shop/en/pools/contactForm>

Hayward Pool Products P.O. Box 5100 Clemmons, NC 27012-5100, Phone: 908-355-7995

To our customers, the Serial Number is a 17 digit number, preceded by letters "SN"

The Serial# Code: 21121005456789001

- First 2 digits are "21", conforming to UCC-128 symbology, signifying a serial #
- The 3rd – 4th digits are the manufacturing "plant" code (12 for Clemmons, 21 for Wuxi, China)
- The 5th – 8th are "year & month" of the date of manufacture and assembly
- The 9th – 17th are "unique serialized number" for each product


Tested to APSP 16 2017 per Section 1404 of the Virginia Graeme Baker Act (VGB) Pool & Spa Safety Act. Tested by IAPMO, 5001 E. Philadelphia Street, Ontario, CA 91761 (909)-472-4100 in July 2020. Certificate at: [http://pld.iapmo.org/file\\_info.asp?file\\_no=0006353](http://pld.iapmo.org/file_info.asp?file_no=0006353)

Date of Installation: \_\_\_\_\_

Suction outlet components have a finite life, the cover/grate should be inspected frequently and replaced at least every **7 years** or if found to be damaged, broken, cracked, missing, or not securely attached. All other components must be replaced at least every **28 years** or if found to be damaged, broken, or cracked. The screws must be replaced every time a cover is replaced.

Hayward Pool Products acknowledges that it is a federal crime to knowingly and willingly make materially false, fictitious, or fraudulent statements, representations, or omissions on this certification.

The Cover and Sump combination are rated at the following		
MAXIMUM ALLOWABLE FLOW RATES		
<b>WG1031BHF2</b>	9" x 9"	GPM
2 1/2" Side Port Floor Mounted		172
3" Side Port Floor Mounted		264
2 1/2" Bottom Port Wall Mounted		224
3" Bottom Port Wall Mounted		224
2 1/2" Side Port Wall Mounted		184
3" Side Port Wall Mounted		224



**Serial Number**

### ⚠ Warning – Suction Entrapment Hazard.

Suction in suction outlets and/or suction outlet covers which are installed in a small area and/or below the surrounding surface can cause severe injury or death due to body entrapment hazard.

To reduce the risk of body entrapment, installation of the field fabricated sumps must be such that the top of the mounted cover is a minimum of 1 1/2" above the finished pool surface over an area larger than 40" on a diagonal.